

Appendix A

Fish Passage Conditions

Appendix A to the Meadowdale
Beach Park and Estuary Restoration
Effectiveness Monitoring Year 3
Report 2026



Photo A-1

Watercress dominant on the north side of the estuary, April 2025 (looking west)



Photo A-2

Watercress dominant on the north side of the estuary, from the same view as Photo A-1, July 2025 (looking west)



Photo A-3
Area before watercress removal



Photo A-4
Area after watercress removal, note visibly unblocked channel